

Repair Parts for Use with V-9502 Pneumatic Valve Actuator Positioner


Description

The V-9502 Pneumatic Valve Actuator Positioners can be reconditioned using the parts listed in the following selection chart.

Refer to the *V-9502 Series Pneumatic Valve Actuator Positioners Product Bulletin (LIT-977265)* for important product application information.

Selection Chart

Code Number	Callout	Description
C-9506-1	A	Positioner Movement Complete Less Items B and C
D-9502-604	B	Operating Span Lever Arm Assembly
Refer to the <i>Positioner Springs</i> tables in the <i>V-9502 Series Pneumatic Valve Actuator Positioners Product Bulletin (LIT-977265) Catalog Page (LIT-1924100)</i> .	C	Springs



Repair Parts, V-9502